



GOVERNMENT OF WEST BENGAL,
DIRECTORATE OF PUBLIC HEALTH ENGINEERING,
OFFICE OF THE EXECUTIVE ENGINEER,
SILIGURI WATER SUPPLY DIVISION,
DISTRICT LABORATORY AT FULBARI,
SILIGURI

PHYSICAL AND CHEMICAL TEST REPORTS :


Date Of Collection	12.06.2019
Date Of Analysis	12.06.2019
Date Of Reporting	12.06.2019


SL. NO.	Parameters	Acceptable Limit	Cause of Rejection	RESULT	
				Place	Doon Heritage School, Kolabari, Debidanga
				Source	Boring after Filtration
				Sender	Principal, Doon Heritage School
1.	Turbidity (NTU)	1	10	1.54	
2.	pH	7.0 to 8.5	<6.5 or >9.2	6.71	
3.	TDS(ppm)	500	2000	101	
4.	Colour(Hz)	5	25	0	
5.	Iron (mg/l)	0.1	1.0	0.02	
6.	Chlorine (mg/l)	0.2	>1.0	0	
7.	Fluoride (mg/l)	1.0	1.5	0	
8.	Total Hardness(mg/l)	300	600	68	

*The tests done with the Sample as deposited by the Party.

Physical & Chemical Test Charge @ Rs. 900.00/ Sample


Chemist/Bacteriologist,
District Laboratory,
Fulbari, W.T.P.



Junior Engineer,
Siliguri Water Supply Division,
P.H. Engineering Dte.


Assistant Engineer,
Siliguri Water Supply Division,
P.H. Engineering Dte.

Memo No.....458/1...../SD: Dated, Siliguri, the...17-6.....2019

Copy forwarded for information and necessary action to:-

1. The Principal, Doon Heritage School.
2. Office Copy.


Executive Engineer,
Siliguri Water Supply Division,
P.H. Engineering Dte.

June-09